

Product Bulletin

CLAAS of America Inc.

8401 South 132nd Street, Omaha,
NE 68138
Phone: 402-861-1000
Fax: 402-861-1003

Issue no. 37 / January 2010

PM Information: Lincoln Quicklub® Automatic Lubrication System availability ex factory for 500 Series LEXION rotor combines

The following new options can be equipped on 500 Series LEXION rotor combines:

- **R05 0030 Lincoln Lube Greasing System**
 - 590R, 580R, 570R, 560R

- **R05 0035 Lincoln Lube Greasing System – with MTS**
 - 595R, 585R, 575R

Please note: The Lincoln Lube automatic greasing system will be limited in availability during the 2010 model year – not available for 570 walker machines. The available systems will be allocated on a first come, first serve basis.



2010 List Pricing:

Optional Equipment -- Order As Desired			
Automatic Greasing System			
R05 0030	Lincoln Lube Automatic Greasing System Automatic greasing system for machines with front tires	\$	7,600
R05 0035	Lincoln Lube Automatic Greasing System -- with MTS Automatic greasing system for machines with MTS	\$	8,900

Product Bulletin

Key Features and Benefits:

- Over 95% of the lubrication points are supplied with a precise volume of grease
- Lube points are consistently lubricated throughout the harvest day
- Contaminants are “pushed” out from bearings when greased
- Confidence in knowing maintenance is completed on a consistent basis
- Reduce labor expense during routine maintenance intervals
- Increased trade-in value

* Please note: Not all lubrication points are supplied with the grease. For example, rotating variable speed pulley sheaves as well as all front attachments are not supplied with grease.

Service, Parts and Warranty:

For parts and service including warranty, please contact your local Lincoln Lube dealer. Lincoln Lube parts will not be stocked in the CLAAS Parts distribution system. For technical support or questions on maintaining your Lincoln Lube system, please contact Lincoln Lube directly at:

- 314-679-4200 extension 4782
- Bob Tanner, National Account Manager, cell: 314-651-8223
- www.lincolnlube.com

Accessibility:

The Lincoln Quicklub® Automatic Lubrication System is strategically located in the sealed LEXION Battery Box for rapid servicing and manual over-ride for troubleshooting.

